



Accident & Title History

<u>Check Records</u>



Market Value Fair Price

<u>Check Records</u>

<u>Check Records</u>

Service & Repair History



Odometer Records Check

<u>Check Records</u>



VIN: 1GBLP37J9W3311057

CHEVROLET

🛱 Runs & Drives / 🔿 Engine Starts / 🔩 Has Keys



| Auction Info | |
|------------------------|---------------------------|
| Seller Type | Unlisted |
| Auction Date | March 1, 2021 1:00 PM CST |
| Location | Phoenix, Arizona |
| Buyer Country | United States |
| Vehicles Sales History | |
| | |

| Title & Condition | | | |
|-------------------------------|------------------------------|--|--|
| Title Type | Salvage | | |
| Title Description | AZ - Cert Of Title - Salvage | | |
| Primary Damage | Burn | | |
| VIN | 1GBLP37J9W3311057 | | |
| Technical Specs | | | |
| Odometer : | 78,530 miles on title | | |
| Estimated Repair Cost : | \$10,357 | | |
| Avg. Estimated Retail Value : | \$18,640 | | |
| Damage Ratio : | 54% | | |
| Estimated Winning Bid : | \$6,878 - \$8,406 | | |
| Body Style : | Recreational Vehicle | | |
| Color : | White | | |
| Engine Type : | 8 | | |
| Fuel Type : | Gas | | |
| Cylinders : | 8 | | |
| Transmission : | Automatic | | |
| Drive : | Rear-Wheel Drive | | |
| Engine : | 7.4L V8 OHV 16V | | |
| Trim : | P30 | | |
| Made In : | United States | | |

Vehicle Style :

Motorhome

Details info. on VIN: 1GBLP37J9W3311057

Year: 1998

Make: CHEVROLET

Body: Incomplete - Motor Home Chassis

Model: Motorhome Chassis

Vehicle type: INCOMPLETE VEHICLE

Error Code: 0

Error Text: 0 - VIN decoded clean. Check Digit (9th position) is correct

Vehicle Descriptor: <a>1GBLP37J*W3

Manufacturer Name: GENERAL MOTORS LLC

Plant City: DETROIT

| Made: UNITED STATES (USA) | Plant Company Name: GM Truck Group | |
|---|---|--|
| Weight: Class 5: 16,001 - 19,500 lb (7,258 - 8,845 kg) | Plant State: MICHIGAN | |
| Series: Forward Control | Trim2: 1 ton nominal | |
| Vin: 1GBLP37J9W3311057 | Trailer Type Connection: Not Applicable | |
| | Drive Type: 4x2 | |
| Brake System Type: Hydraulic | | |
| Engine Number of Cylinders: 8 | | |
| Displacement (CC): 7400.0 | | |
| Displacement (CI): 451.57570630101 | | |
| Displacement (L): 7.4 | | |
| Engine Configuration: V-Shaped | | |
| Fuel Delivery / Fuel Injection Type: Multipoint Fuel Injection (MPFI) | | |
| Other Engine Info: HO | | |
| Engine Manufacturer: WRN | | |
| Source: Vpic | | |
| | | |

Selling your Vehicle?

The sticker on the window is a rich source of essential information about your automobile. The window sticker lets your buyer know exactly what's included particularly in your car.



This information can help you make strategic decisions about bidding and budgeting by showing you where you're succeeding and where you may be missing opportunities for improved performance.

Upgrade your Report

© 2021 MVC. All rights reserved.